



BLUE BIRD

SERVICE MEMORANDUM

NO. SM1314

MEMO TO: All Blue Bird Dealers

SUBJECT: Malfunction Indicator Lamp and/or Engine Warning Lamp “ON” With Cummins Engine Fault Codes 3558, 3559, Both Active Together.

MODEL YEAR(S): 2014

MODEL(S) AFFECTED: Vision and All American with ISB 2013–Emission Diesel Engines

Cummins has released software calibration update improvements to reduce occurrence of engine malfunction indicator lamp and check engine lamp “ON” with Cummins fault codes 3558 and 3559 both active together.

3558: Aftertreatment Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source.

3559: Aftertreatment Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source.

If your bus has an engine with a Cummins manufacture date earlier than listed below, a software calibration revision is available. Please contact your local Cummins repair facility.

Cummins Engine Build Dates:

ISB6.7 CM2350 – August 16, 2013

Cummins Engine Calibrations Must Be Equal To Or Higher Than Revisions Listed:

ISB6.7

ECM Code
DT90009.19
DT90002.20
DT90025.12
DT90004.20
DT90006.20
DT90034.12

BLUE BIRD BODY COMPANY

P.O. Box 937 – 402 Blue Bird Blvd – Fort Valley, Georgia – (478) 825-2021